




VINDÖ 90










VINDÖ 90

DATA

L.O.A. 13,00 m
 Beam. 3,95 m
 L.W.L. 9,75
 Draft. 1,75 m
 Ballast 4,50 Ton
 Displac. 15,00 Ton

Main 35,3 m²
 Jib 23,0 m²
 Storm jib 15,0 m²
 Genoa I 49,0 m²
 Genoa II 42,5 m²
 Mizzen 12,2 m²
 Spinnaker 95,0 m²

Motor: Volvo Penta MD 21, 51 hp
 alt. MD 40, 6 cyl. 85 hp
 Tank: Diesel ≈ 600ltr
 Water ≈ 600ltr







Toilet fore cabin



Toilet owners cabin



Nötesunds Varv AB Schweden

440 90 Henån, Tel. 0304-392 90, Telex: 21233 vindoe S.

Verkaufsbüro Deutschland:

Bezirk Kiel:
Bezirk München (auch Österreich):
Bezirk Berlin:
Bezirk Essen:
Bezirk Flensburg:

Sales Offices:

Denmark:
Finland:
Italy:
United Kingdom:
USA:

Roland Engert, Wackerweg 5, 2 Hamburg 52, Tel. 040-803975, Telex: 214945 nva D.

VINDO Yacht-Service und Handelsgesellschaft mbH, Hinter der Schönbergerstrasse 32/34, 2300 Kiel 14, Tel. 0431-723057, 723058.

Karl Drexel, Wilsdatter Strasse 42, 8 München 50, Tel. 089-812 36 06, Telex: 52 12 847.

Jürgen Ehlers, Fröhnerstrasse 11/13, 1 Berlin 20, Tel. 030-3612407.

Hubert Werres, Werner Aoe 6, 43 Essen-Steele, Tel. 0201-536586.

Fred Burs, Am Leuchtturm 2, 2392 Glücksburg-Schauseende, Tel. 04631-2335.

Kjeller Mørne, Strandboulevarden 110, 2100 København Ø, Tel. 01-421295.

VINDO-Marine, Lönnrotsgal. 9 A, Helsingfors 12, Tel. 90-607790, 646911.

Franco Scordamaglia, Via Vita 56, 38050 Villazzano(TN), Tel. 0461-924453, 988202, Telex: 400828.

Tollsbury International Marine, Woodroffe Road, Tollsbury, Essex CM9 8SE, Tel. 062-1868264/1868249.

West Coast Agent: Rolf Björner, 1900N, Northlake Way, Suite 113, Seattle, Washington 98103, Tel. 206-632-9494.

South Coast Agent: Gordon R. MacLeod, 216 Lakewood Drive, Rockwall, Texas 75087, Tel. 214-722-3803.

Great Lakes Agent: Carl Engman, 537 S. Dryden Place, Arlington Heights, Illinois 60005, Tel. 312-267-0733, 312-386-1662.

På bilderna kan förekomma utrustning som ej är standard. On the photos may appear some equipment, which is not standard. Die Photos entsprechen nicht unbedingt der Standardausrüstung.



Nötesunds Varv AB
Sweden